

Service Bulletin

July 9, 2009

Mis-wired Molex Plugs on Economizers

Shipments of part numbers DNECONGS90150, HZECONGS90150, DNECONHP90150 and HZECONHP90150 have wires in the incorrect positions in the Molex plug intended to connect the economizer to the package unit. The unit will not function with the incorrect wiring connected.

There are two remedies to the problem:

- 1) Remove the Molex plugs from the economizer and unit and hard wire it using the wiring diagram provided with the economizer.
- 2) Contact McDaniel Metals to acquire a wiring harness adapter. This adapter consists of a male and female Molex plug that converts the correctly wired Goodman unit plug to the incorrectly wired economizer plug.

The wiring harness adapters are available free of charge and will ship UPS Next Day Air.